

Oil Field Environmental Incident Summary

Incident: 20141209163539 **Date/Time of Notice:** 12/09/2014 16:35

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BEAVER LODGE-DEVONIAN UNIT I-315

Field Name: BEAVER LODGE

Well File #: 1636

Date Incident: 12/9/2014

Time Incident: 11:00

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 95

Sec: 17

Qtr:

Location Description: Slight mist of emulsion ontop of the snow north of location (stubble field) in an area approx. 12 ft. x 75 ft.

Submitted By: Troy Brunsell

Received By:

Contact Person: Jason Henry
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	1.5	Barrels			1.5	barrels

Description of Other Released Contaminant:

Emulsion

Inspected:

Written Report Received: 12/1/2015

Clean Up Concluded: 12/19/2014

Risk Evaluation:

Snow, stubble in field

Areal Extent:

12 ft. x 75 ft. (mist ontop of the snow in stubble field)

Potential Environmental Impacts:

Topsoil

Action Taken or Planned:

Well has been isolated to replace packing and a cleanup crew will be dispatched to cleanup the impacted area.

Wastes Disposal Location: Approved waste disposal

Agencies Involved:

Updates

Date: 12/10/2014 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Inspected site. Emulsion from stuffing box leak appears around well site and in the field to the north. Two separate areas of darkened vegetation were apparent extending an estimated 100 ft into the field. Cleanup has not occurred yet. Left voicemail for company contact requesting a cleanup plan. Unknown who owns the land and if a separate landowner has been contacted yet.

Date: 12/10/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Stuffing box leak sprayed oil/produced water emulsion into a stubble field. Followup is necessary.